Photomontages - Hillas Farm (Dwelling V23)

Existing view



Design HLE033 - photmontage



Design HLE033 - highlighted towers







Humelink Landscape and visual impact assessment

Photomontages - View from garden



























Hillas Farm (Dwelling V23)

Photomontages - View from garden

Photomontages - Hillas Farm (Dwelling V23)

Existing view



Design HLE033 - photmontage



Design HLE033 - highlighted towers



Note, the extent of vegetation clearing within the corridor is not known and has not been shown on these photomontges.





Humelink Landscape and visual impact assessment

Photomontages - View from near Homestead verandah

























